1. DESCRIPTION

The BA507E-SS and BA527E-SS are panel mounting general purpose digital indicators which are housed in rugged stainless steel enclosures. They are loop powered by the 4/20mA input which they display in engineering units.

The two models are electrically similar, but have different size displays.


Model	Display
BA507E-SS	4 digits 15mm high
BA527E-SS	5 digits 12.7mm high and bargraph.

This abbreviated instruction sheet is intended to installation and commissioning, a comprehensive instruction manual describing system design and calibration is available from the BEKA sales office or may be downloaded from the BEKA website www.beka.co.uk/manuals.html

2. INSTALLATION

Both models have front panel impact and IP66 ingress protection but should be shielded from direct sunlight and severe weather conditions. The rear of both indicators have IP20 ingress protection.


Panel cut-out 90 +0.5 / -0.0 x 43.5 +0.5 / -0.0



Connect M4 earth stud to panel enclosure in which indicators is mounted


Fig 1 cutout dimensions & terminals

Abbreviated instructions for BA507E-SS & BA527E-SS rugged general purpose panel mounting loop powered indicators



Issue 4 16th May 2023

BEKA associates Ltd. Old Charlton Rd, Hitchin, Hertfordshire, SG5 2DA, UK Tel: +44(0)1462 438301 Fax: +44(0)1462 453971 e-mail: sales@beka.co.uk web: www.beka.co.uk



a stainless steel washer and wing nut, tighten 22cNm (1.95lbf in) min. Finally fit protective caps.

Fig 2 Installation procedure

EMC

For specified immunity all wiring should be in screened twisted pairs, with the screens earthed at one point





Fig 3 Typical measurement loop

Scale card

The indicator's units of measurement are shown on a printed scale card visible through a window at the right hand side of the display. The scale card is mounted on a flexible strip that is inserted into a slot at the rear of the instrument as shown below.



g 4 Inserting flexible strip carrying scale card into slot at the rear of indicator

Thus the scale card can easily be changed without removing the indicator from the panel or opening the instrument enclosure.

New indicators are supplied with a printed scale card showing the requested units of measurement, if this information is not supplied when the indicator is ordered a blank card will be fitted.

A pack of self-adhesive scale cards printed with common units of measurement is available as an accessory from BEKA associates. Custom printed scale cards can also be supplied.

To change a scale card, unclip the protruding end of the flexible strip by gently pushing it upwards and pulling it out of the enclosure. Peel the existing scale card from the flexible strip and replace it with a new printed card, which should be aligned as shown below. Do not fit a new scale card on top of an existing card.




Fig 5 Fitting scale card to flexible strip

3. OPERATION

The indicators are controlled via four front panel push buttons. In the display mode i.e. when the indicator is displaying a process variable, these push buttons have the following functions:

- While this button is pushed the indicator will display the input current in mA, or as a percentage of the instrument span depending upon how the indicator has been conditioned. When the button is released the normal display in engineering units will return. The function of this push button is modified when optional alarms are fitted to the indicator.
- While this button is pushed the indicator will display the numerical value and analogue bargraph* the indicator has been calibrated to display with 4mA input. When released the normal display in engineering units will return.
- While this button is pushed the indicator will display the numerical value and analogue bargraph* the indicator has been calibrated to display with 20mA input. When released the normal display in engineering units will return.
- No function in the display mode unless the tare function is being used.
- P + ▼ Indicator displays firmware number followed by version.
- P + ▲ When optional alarms are fitted provides direct access to the alarm setpoints if the 'ACSP' access setpoints in display mode function has been enabled.
- P + E Provides access to the configuration menu via optional security code.

The BA507E-SS and BA527E-SS are CE marked to show compliance with the European EMC Directive 2014/30/EU. They are also UKCA marked to show compliance with UK Electromagnetic Compatibility Regulations UKSI 2016:1091 (as amended)


^{*} Only the BA527E-SS has a bargraph

4. CONFIGURATION

Indicators are supplied calibrated as requested when ordered, if not specified default configuration will be supplied but can easily be changed on-site.

Fig 6 shows the location of each function within the configuration menu with a brief summary of the function. Please refer to the full instruction manual for detailed configuration information and for a description of the lineariser and the optional dual alarms.

Access to the configuration menu is obtained by pressing the P and E buttons simultaneously. If the indicator security code is set to the default '0000' the first parameter 'FunC' will be displayed. If the indicator is protected by a security code, 'CodE' will be displayed and the code must be entered to obtain access to the menu.



Function

Display

mode

9999

Ė

CodE

or to select Standard function Root extractor

Lineariser

Resolution

diait

Security Code

Enter code by

pressing

▲ or ▼ & P to move to next

digit. Code 0000 allows direct

or ▲ or ▼ to select to select position of resolution of least dummy significant decimal point

Decimal point Calibration using external current source (Preferred method)

> With accurate 4mA input current set required zero display by pressing or and to move to the next digit

Similarly, using accurate 20mA input current set required full scale display

Any current between 4 and 20mA may be used providing difference is > 4mA

Calibration using internal references (Input current may be any value)

Using ZEro function set required display at 4mA by pressing or ▼ and P to move to the next digit

Similarly, using SPAn function set required display at 20mA

Select type of bargraph display and define start and finish relative to digital display

Using the tYPE function select required bargraph justification by pressing (A) or (V)

Using the bArLo function set the digital display at which the bargraph is required to start by pressing or and b to move to the next digit. Similarly using the bArHi function set digital display at which the bargraph is required to finish

Function of P button in

Press

display mode

or to toggle between 4-20mA and % of span

Tare Function

Press or ▼ to turn tArE on or oFF

Define Security Code

Enter by pressing a or and P to move to next digit

Reset indicator configuration

Press or 🔻 to select ConF to reset indicator or LtAb to reset lineariser to default

> Confirm selection by entering SurE by pressing ▲ or ▼ and P to move to next digit

configuration.



Manuals, certificates and datasheets can be downloaded from http://www.beka.co.uk/lpi7/

